

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



Photo #5276 from entrance to location.



Photo #5279 Condensate tank missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



Photo #5278 Location lacks stabilization.



Photo #4163 from inspection #699803279 conducted on 6/24/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



Photo #5277 Location lacks stabilization.



Photo #4162 from inspection #699803279 conducted on 6/24/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



Photo #5280 No form of tracking BMP at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources