

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2021

Submitted Date:

11/30/2021

Document Number:

701600508

FIELD INSPECTION FORM

Loc ID: 303562 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 75027
Name of Operator: ROSEWOOD RESOURCES INC
Address: 2101 CEDAR SPRINGS RD STE 1500
City: DALLAS State: TX Zip: 75201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|-----------------------------|
| Dolezal, Pat | | pat.dolezal@ownresources.com | Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253293 | WELL | PR | 02/12/1987 | GW | 125-07170 | NEWBANKS 2-14 | PR |

General Comment:

Routine FIR - SATISFACTORY Change of Operator Doc#402406906 approved 11/17/2021

Location

| | | | |
|--------------------|---------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track grassland | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No
 Comment: NONE

Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Steel panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----------|-------|-----------------|
| Equipment: | | | |
| Type: Other | # 0 | | corrective date |
| Comment: | No change | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 253293 Type: WELL API Number: 125-07170 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | In Process | Other | In Process | | | |

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT