

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2021

Submitted Date:

12/01/2021

Document Number:

700703599

FIELD INSPECTION FORM

Loc ID 335277 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211446	WELL	PR	05/20/2015	GW	045-07206	GIBSON GULCH UNIT 13-30	PR
268445	WELL	PR	09/06/2003	GW	045-09259	GIBSON GLCH UNIT 12-30	PR
270374	WELL	PR	04/26/2005	GW	045-09540	GIBSON GULCH UNIT 12-30 D	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 11/30/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP GGU 13-30, at Location # 335277 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area and 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. South side of location show signs of erosion.
2. Tank secondary containment liner is failing. See photos.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Horizontal units that include glycol storage tanks, storage vessels have labeling.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient		Inadequate
Comment:	Tank secondary containment liner is failing. See photos.			
Corrective Action:	Install or maintain liner material to ensure spill or released materials will be maintained with containment structure.			Date: 01/07/2022

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211446 Type: WELL API Number: 045-07206 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 268445 Type: WELL API Number: 045-09259 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 270374 Type: WELL API Number: 045-09540 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Waddles				

Comment: 1. South side of location show signs of erosion.

Corrective Action: Install or repair required BMPs

Date: 01/07/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703605	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593016