

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2021

Submitted Date:

12/01/2021

Document Number:

690102735

FIELD INSPECTION FORMLoc ID 329434 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244129	WELL	PA		GW	123-11922	SMITH 1	PA
249545	WELL	SI	09/01/2017	GW	123-17348	SMITH 9-5	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected FacilitiesFacility ID: 244129 Type: WELL API Number: 123-11922 Status: PA Insp. Status: PAFacility ID: 249545 Type: WELL API Number: 123-17348 Status: SI Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline DescriptionFlowline Type: Non-Well Site Size: 2" Material: Carbon Steel

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)
☐ 1101. Installation and Reclamation
 ☒ 1102. Operations, Maintenance, and Repair
 ☐ 1103. Abandonment

Comment: Well is plugged and abandoned (Smith 1/ 2019); Well (Smith 9-5) is currently SI status. Signage at battery indicates location is shut in (long term). OOSLAT (locks and tags) in place on off location flowline valve at wellhead (9-5) and inlet to heated horizontal separator (flowline manifold). No operator personnel were on location during inspection.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102739	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593648
690102740	Flowlines at inlet to HHS (OOSLAT)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593649