

**Inspection Photos**  
**Operator: Arkoma Operations**  
**API: 067-05464**  
**Date: 11/30/2021**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope, from the southwestern corner facing northward. Revegetation is progressing with sagebrush, western wheatgrass, and Indian ricegrass.



Photo 3. View of erosional scouring within diversion channel in southeastern project area. Cobble and sediment are washed down-slope from the diversion.



Erosion occurring beneath wattle. Wattles not trenched

Photo 4. View of bare/unstabilized soils on the eastern cut-slope. Wattles are not adequate BMPs here.



Photo 5. View of reference area comprised of sagebrush shrubland, with snakeweed, buckwheat, western wheatgrass, Indian ricegrass, purple threeawn, and squirreltail.