

Inspection Photos
Operator: Logos Operating
API: 067-08272
Date: 11/30/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is largely progressing here with sagebrush, western wheatgrass, and sand dropseed. Portions of the fill slope remain weedy and rilling observed.



Photo 3. View of the western cut-slope. Slope is not stabilized, with rills approximately 8-12 inches deep. Diversion ditch is full of sediment.



Photo 4. View of the northern cut-slope. Bare soils on steep slope need stabilization.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of western wheatgrass, Indian ricegrass, black sage, prickly pear, and purple threeawn.