

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2021

Submitted Date:

12/02/2021

Document Number:

697601729

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Contact Information:

Contact Name	Phone	Email	Comment
Rowley, Taylor		Taylor_Rowley@oxy.com	
inspections, All		COGCCInspections@Oxy.com	
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
149021	CENTRALIZED EP WASTE MGMT FAC	AC	07/16/2008		-	DRILLING FLUID MANAGEMENT FACILITY	EI

General Comment:

Site is no longer in use for treatment or disposal of water based drill fluids and/or cuttings.

Ongoing site investigation and remediation project 18646 is open to document the closure of the centralized E&P waste management facility.

Attached photos document conditions at the facility. All areas used as part of the E&P waste management facility have been tilled and all appear to have been seeded with some germination noted at this time. Photos were taken from active well locations on the property.

Retention pond at southwest corner has been removed and has also been tilled and seeded,

Inspected Facilities

Facility ID: 149021 Type: CENTRALIZE API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [facility closure site investigationa and remediation project 18646 at this facility is underway. Reclamation plan with respct to rule 915.b complaince has been proposed by operator.](#)
[Further sampling and analysis after one crop cycle is proposed by operator.](#)

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601730	facility sign at entrance gate.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594993
697601731	photos of crop fields from well locations	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594994