

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2021

Submitted Date:

11/22/2021

Document Number:

695105221**FIELD INSPECTION FORM**Loc ID 309562 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300078	WELL	SI	07/01/2021	GW	071-09697	Redbud 44-7	SI
301618	WELL	AL	06/27/2011	LO	071-09755	REDBUD 44-7TR	AL

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PIT

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: **TELEMETRY EQUIPMENT**

Corrective Action:

Date:

Type: Bradenhead

1

Comment: **IS PLUMBED TO SURFACE**

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: **CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.**

Corrective Action:

Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 300078 Type: WELL API Number: 071-09697 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 301618 Type: WELL API Number: 071-09755 Status: AL Insp. Status: AL**Producing Well**Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 426708Lat: 37.267020Long: -104.813600Reference Point: SEOther: Length: 70Width: 30**Lining:**Liner Type: Liner Condition: AdequateComment: PHOTO 3: pit liner compromisedCorrective (Rule 910). contact COGCC EPS staff for directives.Date: 11/24/2021**Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: NONECorrective Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date:

Permit:	Facility ID	Permit Num	Expiration Date
	426708	2221338	<input type="text"/>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105222	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595049