

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2021

Submitted Date:

11/22/2021

Document Number:

695105225

### FIELD INSPECTION FORM

Loc ID 333670 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name            | Phone | Email                      | Comment                         |
|-------------------------|-------|----------------------------|---------------------------------|
| Distribution, Evergreen |       | cogcc.evergreen@enrllc.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 273555      | WELL | PR     | 04/01/2021  | GW         | 071-08190 | STEALTH 22-5    | PR          |
| 279787      | WELL | PR     | 10/12/2005  | GW         | 071-08527 | STEALTH 22-5 TR | PR          |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type               | Area   | Volume | corrective date |
|--------------------|--|--------|-----------------|
| Gas Meter Run      | # 2  |        |                 |
| Comment:           | BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR. |        |                 |
| Corrective Action: |  |        | Date:           |
| Bradenhead         | # 2  |        |                 |
| Comment:           | BOTH ARE PLUMBED TO SURFACE  |        |                 |
| Corrective Action: |  |        | Date:           |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 273555 Type: WELL API Number: 071-08190 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 279787 Type: WELL API Number: 071-08527 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: [PHOTO 3: OILY WASTE IN ORIGINAL WELL PRIME MOVER ENGINE SKID.](#)

Corrective Action: **COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181 . CA DATE 4-6-21. (IT DOES NOT APPEAR THAT CA WAS ADDRESSED, THERE IS AN ACTIVE LEAK FROM HYRAULIC MOTOR. LEAK NEEDS TO BE REPAIRED IMMEDIATELY OR SKID WILL HAVE TO BE MODIFIED TO PROTECT WILDLIFE).**

Date: 04/04/2021

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 280187      Lat: 37.290321      Long: -104.807078

Reference Point: SE      Other: \_\_\_\_\_      Length: 70      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective Action

\_\_\_\_\_

Date:

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

Type: Produced Water      Lined: NO      Pit ID: 281837      Lat: 37.290129      Long: -104.807676

Reference Point: SE      Other: \_\_\_\_\_      Length: 70      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: **NONE**

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 280187      | 1140641    |                 |
|         | 281837      | 1393880    |                 |

| <b>COGCC Comments</b>   |          |            |
|---|----------|------------|
| Comment   | User     | Date       |
| THIS IS A FOLLOW UP TO INSP. DOC #695104150, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181 . CA DATE 4-6-21. (IT DOES NOT APPEAR THAT CA WAS ADDRESSED, THERE IS AN ACTIVE LEAK FROM HYRAULIC MOTOR. LEAK NEEDS TO BE REPAIRED IMMEDIATELY OR SKID WILL HAVE TO BE MODIFIED TO PROTECT WILDLIFE). THIS IS THE SECOND NOTICE FOR THIS CA. | beardslt | 11/22/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--------------|---|
| 695105226    | INSP. PHOTOS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595051</a> |