

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Gas Meter Run		# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:
Type: Vertical Separator		# 2		
Comment:				
Corrective Action:				Date:
Type: Prime Mover		# 1		
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked		# 6		
Comment:				
Corrective Action:				Date:
Type: Bradenhead		# 2		
Comment:	IS PLUMBED TO SURFACE			
Corrective Action:				Date:
Type: Progressive Cavity		# 1		
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment		# 2		
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:				Date:
Type: Pump Jack		# 1		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 273781 Type: WELL API Number: 071-08211 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 280358 Type: WELL API Number: 071-08551 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:
 Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 288827 Lat: 37.281700 Long: -104.809300
 Reference Point: SE Other: _____ Length: 70 Width: 30

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment:
 Corrective Action Date: _____

Fencing:
 Fencing Type: Wildlife Fencing Condition: Adequate
 Comment:
 Corrective Action Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: NONE
 Corrective Action Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES
 Comment:
 Corrective Action Date: _____

Type: Produced Water Lined: NO Pit ID: 278513 Lat: 37.281930 Long: -104.810968
 Reference Point: SE Other: _____ Length: 70 Width: 30

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment:
 Corrective Action Date: _____

Fencing:
 Fencing Type: Wildlife Fencing Condition: Adequate
 Comment:
 Corrective Action Date: _____

Netting:

Netting Type:	Netting Condition:	
Comment:	NONE	
Corrective Action:		
Anchor Trench Present: <u>NO</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective Action:		
		Date:

COGCC Comments		
Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695104154, CA'S HAVE BEEN ADDRESSED.	beardslt	11/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105228	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595052