

TEP
Clough 31-23H
Location # 323919



location



location

TEP
Clough 31-23H
Location # 323919



location



Load line missing bull plug/cap



TEP
Clough 31-23H
Location # 323919



Glycol vessel lacking labeling



Erosion leading to the tunneling under berm.

TEP
Clough 31-23H
Location # 323919



One spot of the outlet side of tunneling through berm



One spot of the outlet side and inlet of tunneling through berm



TEP
Clough 31-23H
Location # 323919



Erosion leading to the tunneling under berm.



Erosion leading to the tunneling under berm.

TEP
Clough 31-23H
Location # 323919



Erosion leading to the tunneling under berm.



Erosion leading to the tunneling under berm.

TEP
Clough 31-23H
Location # 323919



Sediment migration from the tunneling occurring.



Sediment migration from the tunneling occurring.

TEP
Clough 31-23H
Location # 323919



Sediment migration from the tunneling occurring



Sediment migration/erosion