

TEP
RWF 33-22
Location # 335367



location



location

TEP
RWF 33-22
Location # 335367



location



Lack of stabilization/erosion/sediment migration



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 33-22
Location # 335367



Lack of stabilization/erosion/sediment migration



Lack of stabilization/erosion/sediment migration



TEP
RWF 33-22
Location # 335367



Lack of stabilization/erosion/sediment migration



Lack of stabilization/erosion/sediment migration



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 33-22
Location # 335367




Lack of stabilization/erosion/sediment migration



Lack of stabilization/erosion/sediment migration

TEP
RWF 33-22
Location # 335367



Glycol vessel lacking labeling



Load lines lacking bull plugs/caps