

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2021

Submitted Date:

12/03/2021

Document Number:

696203397

FIELD INSPECTION FORM

Loc ID 383337 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1001 17TH STREET #1900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383337	LOCATION	AC			-	Cascade Creek 608-43-31	RI

General Comment:

On 12/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy's Creek 608-43-31 location in Garfield County, Colorado.

This inspection is a followup to #696203334 to document compliance with the following corrective actions:
1002.f: Stormwater

Inspection is also a followup to Resolution #402870596 stating corrective action has been completed.

Refer to the "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 383337 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203334 observed that control measures to stabilize the production area, and minimize tracking and offsite sediment transport are missing or insufficient. Inspection required Operator to comply with Rule 1002.f by 11/11/2021. Operator submitted FIRR 402870596 stating CA was addressed on 11/11/2021

It was observed that Operator placed gravel on select sections of the Location; from the entrance, leading around the wells. Control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Corrective action has not been addressed and remains applicable.

Corrective Action: Comply with Rule 1002.f

Date: 11/11/2021

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	291945	1433703	

COGCC Comments

Comment	User	Date
Inspection #696203334 observed that the sediment trap on the east end of the Location was missing an appropriate outlet; control has been reinstalled with an engineered/armored outlet. This portion of the corrective action has been addressed.	trujilloam	12/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203398	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595636