



**Inspected Facilities**

Facility ID: 480564 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: COGCC followup to Operator reported spill 480564: thermoflex pipe failure on Bison O&G pad. Operator has backfilled and reclaimed excavated area. Operator has submitted and COGCC approved a Form 27 for additional investigation related to soil suitability parameters. Additional work will proceed under Remediation Project 21050

Corrective Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_