

Inspection Photos

12/01/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 335647

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



Photo 1: Photos 1-2 taken from the southwest end of the Location. Photos provide overview of the Location from southwest, west, north to northeast. Photos also shows areas on the southwest end of the Location not necessary for production, including the second access road on the southwest end of the Location, have not been reclaimed in accordance with 1003 rules and corrective actions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



December 1, 2021
39.54803296N 108.2106672W

Photo 3: Photo shows the second access road on the southwest end. Areas on the southwest end of the Location not necessary for production, including the second access road on the southwest end of the Location, have not been reclaimed in accordance with 1003 rules and corrective actions

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



Photo 4: Photos example showing control measures to protect/stabilize slopes of the Location remains missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



Photo 6: Photo taken from the slopes on the southeast end of the Location. Though rill erosion previously observed appears to have been repaired, control measures to protect and stabilize the slopes remaining missing or insufficient. Arrow shows sediment discharge due to un-stabilized slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 335647



Photo 8: Photos taken from the two access road entrances on the southeast end of the Location. Photos examples showing control measures to stabilize the Location, and minimize tracking and offsite sediment transport are inadequate, and have not been installed/maintained in proper functioning condition per good engineering practices; tracking and sediment transport observed. Photo left also shows second access road has not been reclaimed.

