

Inspection Photos

12/01/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 1: Photos 1-4 provide an aerial overview of the Location; Location disturbance ~6 acres. Photos show areas not needed for production have not been decompacted, recontoured/regraded and reclaimed; Location has not been reduced to 2 acres per the 2A Location Permit #401387622.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 5: Photo provides example of the fill slopes on the west end of the Location; slopes constructed with a steep grade, with rocky subgrade material. Photo shows control measures to protect/stabilize the slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 6: Photo provides example of the fill slopes on the west end of the Location; slopes constructed with a steep grade, with rocky subgrade material. Photo shows control measures to protect/stabilize the slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 7: Photo provides example of the fill slopes on the east end of the Location; slopes constructed with a steep grade, with rocky subgrade material. Photo shows control measures to protect/stabilize the slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 8: Photo provides example of the fill slopes on the east end of the Location; slopes constructed with a steep grade, with rocky subgrade material. Photo shows control measures to protect/stabilize the slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 9: Photos taken from the southeast end of the Location. Photo shows various concrete waste/debris stored and/or partially buried on the southeast end of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 10: Photos taken from the southeast end of the Location. Photo shows various concrete waste/debris stored and/or partially buried on the southeast end of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 452807



Photo 11: Photos taken from the southeast end of the Location. Photo shows various concrete waste/debris stored and/or partially buried on the cut slope.