

Inspection Photos

API: 009-06441

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 11/30/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 1. Facing southeast toward the location. The access road continues thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 2. There is a plastic pipe at northeast side of the location. This needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 3. There is electrical wires that remain at the southeast side of the location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 4. Facing northeast at the south side of the location. This area consists mostly of undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 5. View of undesirable weeds at the south side of the location. The weed debris needs to be removed and the area reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed reference area which consists of Blue grama, Sand dropseed, Prairie threeawn, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06441 | Date: 11/30/2021