

Inspection Photos
Location Name: Federal 11-90-35 #1
API: 05-051-06059



Flow lines with welded on caps near location entrance.



View from location entrance towards main road. Mini ex in background near other end of flow lines.

Inspection Photos
Location Name: Federal 11-90-35 #1
API: 05-051-06059



Open excavations on location.



Federal 11-90-35 #1 with steel plate welded on.

Inspection Photos
Location Name: Federal 11-90-35 #1
API: 05-051-06059



Identifying information is not present on steel plate.



Guy line anchor and marker observed during this inspection.

Inspection Photos
Location Name: Federal 11-90-35 #1
API: 05-051-06059



Open excavation near main road.



Flow line with caps welded on.

Inspection Photos
Location Name: Federal 11-90-35 #1
API: 05-051-06059



Close up of abandoned flow line.



Cap welded onto abandoned flow line.