

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/06/2021

Document Number:

693803865**FIELD INSPECTION FORM**Loc ID 312441 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hahn, Travis		thahn@maralexinc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221613	WELL	SI	09/01/2011	GW	077-08215	LIPAN WASH UNIT 1-14-2-2	SI

General Comment:

COGCC staff performed a followup field inspection on 12/3/2021. Followup to inspection doc#693801222 on 11/4/2019. Issues were found requiring corrective action. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	
Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Proper sign installed. CA completed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-858-8550 or 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. CA from previous inspection not completed. CA date remains the same as previous inspection.	Date:	11/26/2019
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221613 Type: WELL API Number: 077-08215 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.
CA from previous inspection not completed. CA date remains the same as previous inspection.

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: 39.239309Long: -108.679450Reference Point: SEOther: Length: 20Width: 20**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693803871	Inspection photos 12/3/2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599089