

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Bird Protectors	# 1	STEAL MESH ON TANK BATTERY OPENING			
Progressive Cavity	# 1	HYDRAULIC DRIVE HEAD			
Ancillary equipment	# 1	TELEMETRY EQUIPMENT			
Prime Mover	# 1	GAS MOTOR			
Bradenhead	# 1	IS PLUMBED TO SURFACE			
Vertical Separator	# 1	INSIDE METER HOUSE			
Gas Meter Run	# 1	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.167594,-104.674012
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 217579 Type: WELL API Number: 071-06358 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action: Date:

Pits: NO SURFACE INDICATION OF PIT

Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>112889</u>	Lat: <u>37.167547</u>	Long: <u>-104.674173</u>
Reference Point: <u>SE</u>	Other: <input type="text"/>	Length: <u>120</u>	Width: <u>40</u>	

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action: Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action: Date:

Netting:

Netting Type: Netting Condition:

Comment: NONE

Corrective Action: Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<u>THIS IS A FOLLOW UP TO INSP. DOC #700600262, CA HAS BEEN ADDRESSED.</u>	beardslt	12/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105254	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599207