

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2021

Submitted Date:

12/07/2021

Document Number:

689806700

FIELD INSPECTION FORM

Loc ID 434014 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|--|---------------------------------|
| Boyer, David | 303-994-0000 | david@d90energy.com | |
| Inspections, General | | sandridgeenvironmental@san dridgeenergy.com | All Inspections |

General Comment:

FLIR inspection in response to compliant 402880151. The complainant claimed emissions were observed from tank battery. Emissions were observed from the southeast tank in the battery during COGCC FLIR inspection. Inspector contacted D90 on 12/2/2021 and informed them of the observed emissions. D90 assured inspector that emissions would be addressed immediately. D90 expressed concern of trespassing and tampering during this conversation. Inspector recommended contacting the local sheriff and installing additional security measures on location if tampering/trespass was a safety concern.

