

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/07/2021

Document Number:

689806704

FIELD INSPECTION FORMLoc ID 316742 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	
Eisenach, Jason		jeisenach@phxresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232600	WELL	PR	08/01/2020	OW	107-06013	MARY HITE FEE 1	SI

General Comment:

FLIR inspection in response to compliant 402880130. The complainant claimed emissions were observed at wellhead. COGCC FLIR inspection showed venting occurring at wellhead. Venting was also visible without the FLIR camera. Inspector left voicemail with Phoenix on 12/7/2021 notifying them that venting must cease immediately. FLIR footage from the previous inspection, 7/15/2021 document number 689806018, also documented venting at the wellhead of this location.

Inspected Facilities									
Facility ID:	232600	Type:	WELL	API Number:	107-06013	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.350444 Long: -107.196249Wind: Calm Speed: (mph) Direction From: SW Weather: Clear Temperature: 43 (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:10	AM	11:15	AM	Wellhead(s)

Comment: FLIR inspection in response to complaint 402880130. The complainant claimed emissions were observed at wellhead. COGCC FLIR inspection showed venting occurring at wellhead. Venting was also visible without the FLIR camera.

Corrective Action: Immediately cease venting. Submit Form 4 for review and approval to vent.

Date: 07/17/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
689806705	FLIR footage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599866
689806706	naked eye venting footage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599867