

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/24/2021

Submitted Date:

12/07/2021

Document Number:

688801074

FIELD INSPECTION FORM

Loc ID 324481 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 1801 BROADWAY #1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		geops@oxbow.com	Inspection mail box
Fischer, Alex		alex.fischer@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283921	WELL	PR	06/01/2020	GW	051-06071	HOTCHKISS FEDERAL 12-89 18-31	EI
284076	PIT	AC			-	HOTCHKISS FEDERAL 18-31	EI

General Comment:

On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Federal 12-89 #18-31. For the most recent field inspection report of this facility, please refer to document #699802733.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel fencing around well head and pump jack.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on well sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel enclosure.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Generator		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Combo unit with separator.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283921 Type: WELL API Number: 051-06071 Status: PR Insp. Status: EI

Facility ID: 284076 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection.

Corrective Action: Per Rule 913.c.(1) the operator will submit a Form 27 for closure of Pit Facility ID #284076.

Date: 01/07/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection.

Corrective Action: Per Rule 909.a.(3) the operator will update this Facility status on a Form 15.

Date: 01/07/2022

Pits: NO SURFACE INDICATION OF PIT

Type: Reserve Lined: Pit ID: 284076 Lat: 39.019960 Long: -107.375150

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	284076	1433362	
	284076	1433362	

COGCC Comments

Comment	User	Date
On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Federal 12-89 #18-31. For the most recent field inspection report of this facility, please refer to document #699802733. Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection. Per Rule 909.a.(3) the operator will update this Facility status on a Form 15. Per Rule 913.c.(1) the operator will submit a Form 27 for closure of Pit Facility ID #284076.	hughesjo	12/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801075	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599980