

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/07/2021

Document Number:

693506042**FIELD INSPECTION FORM**
 Loc ID 326264 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	<a href="#">All Inspections per email 8/13/2021</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216136	WELL	PR	03/08/2002	GW	067-07742	CHANEY 1-1	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Debris: Dead weeds along access road		
Corrective Action	Comply with rule 606	Date:	01/07/2022
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Wind wall material around motor in disrepair and laying on ground.		
Corrective Action:	Comply with rule 606	Date:	01/07/2022
Type	DEBRIS		
Comment:	Dead weeds in and around locaiton		
Corrective Action:	Comply with rule 606	Date:	01/07/2022
Type	OTHER		
Comment:	Stained soil around gas motor		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906	Date:	01/07/2022
Type	OTHER		
Comment:	Mechanical issue: gas motor appears to be leaking form motor and exhaust.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	01/07/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	<a href="#">Chain link</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216136 Type: WELL API Number: 067-07742 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/30/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
 On Tuesday December 7, 2021 at approximately 11:04AM I Inspector Randy Silver,  
 conducted an on-site inspection.  
 Location: Chaney #1-1  
 Operator: Enduring resources  
 API#: 067-07742  
 Loc ID: 326264  
 County: LaPlata  
 While there, I observed a producing well site  
 During this inspection the following possible compliance issues were observed:  
 Debris: Rule 606 Corrective action date of 1-7-22 See photos 1,2,3,9,10  
 Trash: Rule 606 Corrective action date of 1-7-22 See photo 5  
 Stained soil: Rule 906 Corrective action date of 1-7-22 See photo 4  
 Mechanical: Rule 608 e Corrective action date of 1-7-22 See photo 4  
 Weather conditions: Cloudy  
 A follow up on this site inspection needs to be conducted to ensure the  
 compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

silverr

12/07/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693506043	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600525">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600525</a>