

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #5326 from entrance to location.



Photo #5327 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #5328 from entrance to location.



Photo #5329 No battery sign located at the tank battery.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #5332 Multiple unmarked storage tanks.



Photo #5333 Sight glass indicates the storage is tank is full of an unknown fluid.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #5334 Storage tank begins at the weld.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #3588 from inspection #699802967 conducted on 4/22/21.



Photo #5330 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #3589 from inspection #699802967 conducted on 4/22/21.



Photo #5331 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #3588 from inspection #699802967 conducted on 4/22/21.