

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402893339

Date Received:
12/08/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
ATWATER BONNIE		batwater@ogrisop.com
Fitzgerald, Edie		efitzgerald@ogrisop.com
Gee, Greg	903-987-0353	ggee@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202109

Inspection Date: 09/28/2021

FIR Submit Date: 09/29/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 309122

Location Name: GOLDEN EAGLE-633S67W Number: 29SESE County: LAS ANIMAS

Qtrqtr: SESE Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.137485 Longitude: -104.904999

FACILITY - API Number: 05-071-00 Facility ID: 288299

Facility Name: GOLDEN EAGLE Number: 29-16

Qtrqtr: SESE Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.137485 Longitude: -104.904999

CORRECTIVE ACTIONS:

1 CA# 156296

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 08/05/2021

Response: CA COMPLETED

Date of Completion: 09/30/2021

Operator Comment: THE WATER IN THE CELLAR WAS PUMPED OUT BY VAC-TRUCK. THE LOCATION WAS BACK DRAGGED TO ELIMINATE THE HARDPAN DISCOLORATION.

COGCC Decision: _____

COGCC
Representative:

2 CA# 156297

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator
Comment:

THE SEDIMENT WAS REMOVED FROM THE CATTLE GUARD. THE LEASE ROAD WAS REGRADED AND THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW. CULVERTS WERE MAINTAINED, SEDIMENT ACCUMULATION REMOVED. ROCK SOCK CHECKS WERE PLACED IN THE BAR DITCH FOR SEDIMENT CONTROL. WATER CALLOUTS WERE INSTALLED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 12/8/2021 4:01:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402893379	PHOTO LOG
-----------	-----------

Total Attach: 1 Files