

GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE MAIN LEASE ROAD WAS SURFACED CROWNED TO CORRECT THE SURFACE EROSION AND CREATE SHEET FLOW.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CATTLE GUARD.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE GRADER.  
ROCK SOCK CHECKS WERE PLACED IN THE FLOW LINE FOR EROSION CONTROL.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



A WATER TURNOUT WAS INSTALL ACROSS THE ROAD FROM THE ROCK SOCK CHECKS. THIS WILL RELIEVE SOME RUN OFF VOLUME FROM THE DOWNHILL SIDE OF THE ACCESS ROAD.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



CULVERT MAINENANCE WAS IMPLEMENTED IN THE CANYON.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE GRADER.  
ROCK SOCK CHECKS WERE PLACED IN THE FLOW LINE FOR EROSION CONTROL.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE GRADER.  
ROCK SOCK CHECKS WERE PLACED IN THE FLOW LINE FOR EROSION CONTROL.



GOLDEN EAGLE 29-16 API# 05-071-09111 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 30, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202109



THE WELLHEAD PACKINGS WERE REPLACED AND THE STUFF BOX WAS SECURELY FASTENED TO STOP THE WATER LEAK. THE LOCATION WAS BACK DRAGGED TO ELIMINATE THE HARDPAN. THE GROUND IS DRY AND NO IMPACTS WERE DISCOVERED.