

Inspection Photos
Operator: Logos Operating
API: 067-05474
Date: 12/7/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with western wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of eastern project area from the northeastern corner facing southward.



Photo 4. View of erosional channeling occurring on the access road, approximately 1.5-2ft wide and deep. Road needs long-term stabilization. Hard had in place for scale.



Photo 5. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, Indian ricegrass, and threadleaf sunflower.