

Inspection Photos
Operator: Simcoe
API: 067-07610
Date: 12/7/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with western wheatgrass, sand dropseed, and crested wheatgrass.



Photo 3. View of western project area from the northwestern corner facing southward.



Photo 4. View of erosional channeling occurring on the access road, approximately 6-12 inches wide and deep. Road needs long-term stabilization. Hard hat in place for scale.



Photo 5. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, Indian ricegrass, and threadleaf sunflower.