

Inspection Photos

12/07/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 452566

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 1: Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 2: Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566




Photo 3: Photo provides example of noxious weeds (plumeless thistle) observed established on the interim areas of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 4: Photos examples showing control measures to protect and stabilize the cut slopes of the Location are missing or insufficient; erosion degradation evident.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 5: Photos examples showing the recently disturbed areas along the west end of the Location; re-seeding evident. Photos show stormwater and erosion control measures to stabilize soils are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 6: Photos provide example of straw wattles observed implemented on the west end of the Location. Photos show wattles have not been installed per good engineering practices; wattles have been placed/staked upon the surface, and have not been trenched and backfilled.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 7: Photos provide example of rock checks / velocity checks observed implemented within the ditch and other areas on the west end of the Location. Rock checks have been constructed with inappropriately sized material, and in such a manner that will facilitate stormwater erosion degradation.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 8: Photo taken from the stormwater diversion ditch on the west end of the Location. Photo shows soils within ditch have not been consolidated in accordance with good engineering practice; soils within ditch are loose, and are considered a pollutant source.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 9: Photo shows what appears to be a bundle of tarp material stored on the northern interim areas of the Location.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452566



Photo 10: Photo example of anchor observed on the Location without proper marking.