

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/24/2021

Submitted Date:

12/02/2021

Document Number:

688801048

FIELD INSPECTION FORMLoc ID 324464 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
		geops@oxbow.com	Inspection mail box
Crockett, Allen		acrocket@blm.gov	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
120678	GAS COMPRESSOR STATION	AC	12/04/2001		-	RAGGED MTN COMPRESSOR STA 120678	EI
211700	WELL	SI	07/01/2021	GW	051-06022	FEDERAL 30-4	EI

General Comment:

On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Federal 30-4. For the most recent field inspection report of this facility, please refer to document #696203170.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign attached to well head.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ragged Mountain Compressor Station sign near silt fence on NE edge of location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign posted near AST.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	AST is labeled with contents, capacity, and has an NFPA placard.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location signs.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		39.156211,-107.477405	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Previous inspections noted that secondary containment berm appeared to have inadequate capacity.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o. Corrective action date taken from Inspection Document #696203025.				Date: 06/24/2021

Wells Served By Facilities Above**AirsID**

API Number
051-06022

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>120678</u>	Type:	<u>GAS</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>211700</u>	Type:	<u>WELL</u>	API Number:	<u>051-06022</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Federal 30-4. For the most recent field inspection report of this facility, please refer to document #696203170. Location is shared with the Ragged Mountain Compressor Station. Previous inspections noted that secondary containment berm appeared to have inadequate capacity. Previous inspection noted sediment pile stored on location. Sediment pile has wattles around the perimeter. No evidence of sediment transport observed during this inspection.	hughesjo	12/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402885485	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594581
688801049	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594580