

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2021

Submitted Date:

12/02/2021

Document Number:

701102290

FIELD INSPECTION FORMLoc ID 334446 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Donahue, Jessica		jdonahue@ardorenvironmental.com	Compliance Specialist
Byers, Jim		jbyers@blm.gov	
,		geops@oxbow.com	Inspection mail box
Johnston, Tyson		Tyson.Johnston@oxbow.com	
Lang, Heather		Heather.Lang@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294808	WELL	PR	01/01/2020	GW	051-06082	DEADMAN GULCH U HOTCHKISS FED 20-12D	PR

General Comment:**COGCC Follow Up Inspection Report Summary**

Location is in close proximity of West Muddy Creek and in a High Priority Habitat Area.

Follow up to 10/18/2021 inspection # 701102071

Uncorrected action item(s)

- No EMS (911) on tank battery sign.
- NFPA label colors are faded on tanks. Separator unit has no contents posted with NFPA label.
- Nearest road is faded. No API # on tank battery sign..
- Legal description is faded on well sign.

Corrected action item(s)

- Chemical container labels replaced
- Braden access and gauge plumbed to above ground surface.
- Pumphouse removed from location, fluids removed from well cellar and secondary containers.

During this inspection the following compliance issues were observed:

- Unused square metal catch container in front of removed pump house has not been removed. Square metal catch container in front of separator is rusted and deteriorating.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Nearest road is faded. No API # on sign.		
Corrective Action:	Install sign to comply with Rule 605.e. Install sign to comply with Rule 605.g.	Date:	01/20/2022
Type	TANK LABELS/PLACARDS		
Comment:	NFPA label colors are faded on tanks. Single unit separator includes a glycol storage tank, Separator unit has no contents posted with NFPA label.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/20/2022
Type	WELLHEAD		
Comment:	Legal description is faded.		
Corrective Action:	Install sign to comply with Rule 605.d. Install sign to comply with Rule 605.g.	Date:	01/20/2022
Type	CONTAINERS		
Comment:	Containers at separator and well head have been labeled. MSDS sheet in battery box at well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: No EMS (911) on tank battery sign.

Corrective Action: Install sign to comply with Rule 605.e.

Date: 11/20/2021

Good Housekeeping:

Type	OTHER		
Comment:	Unused square metal catch container in front of removed pump house has not been removed. Square metal catch container in front of separator is rusted and deteriorating.		
Corrective Action:	Comply with 606	Date:	12/17/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Generator at tanks and separator.		
Corrective Action:		Date:	

Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:	Single unit separator includes a glycol storage tank,	
Corrective Action:		Date:
Type: Prime Mover	# 0	
Comment:	Pump and housing have been removed from location.	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Braden access and gauge plumbed to above ground surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	294808	Type:	WELL	API Number:	051-06082	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing well							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		3 chemical containers 1 at well 2 at separator
Gravel						
Berms						
		Ditches				
Compaction						
		Compaction				
Ditches						
Check Dams						
Seeding						

Comment: Fuild removed from well cellar. Dark fuil removed from chemical container secondary containment at well head.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402885810	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594943
701102292	Inspection 701102290 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5594941