


**Inspection Photos**  
**Location Name: Herring Draw 1-9**  
**Location ID: 392134**



**Photo 1. Overview of location taken facing northeast.  
Stained soil at wellhead.**

