

Inspection Photos
Location Name: Kuipers 1
Location ID: 324629



Photo 1. Overview of location taken facing northeast.



Photo 2. Tank labels faded and peeling.

Inspection Photos
Location Name: Kuipers 1
Location ID: 324629



Photo 3. Stained soil at wellhead.



Photo 4. Stained soil on location.

Inspection Photos
Location Name: Kuipers 1
Location ID: 324629



Photo 5. Stained soil on location.



Photo 6. Stained soil on location. Close up of photo 5.

