

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402895153

Date Received:
12/10/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>
<u>GEE, GREG</u>	<u>903-987-0353</u>	<u>ggee@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695105030
Inspection Date: 10/22/2021 FIR Submit Date: 10/22/2021 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309199

Location Name: NEW ELK-633S68W Number: 36SWNE County: LAS ANIMAS
Qtrqtr: SWNE Sec: 36 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.128291 Longitude: -104.944308

FACILITY - API Number: 05-071-00 Facility ID: 290090

Facility Name: NEW ELK Number: 36-7
Qtrqtr: SWNE Sec: 36 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.128291 Longitude: -104.944308

CORRECTIVE ACTIONS:

1 CA# 157093

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. Date: 10/29/2021

Response: CA COMPLETED Date of Completion: 12/03/2021

Operator Comment: THE LEAK ON THE COMPRESSOR WAS REPAIRED AND THE FLUID ACCUMULATION WAS REMOVED 11/04/2021. A NEW LEAK WAS DETECTED PARTS WERE ORDERED AND REPLCED. UNIT WAS MONTORED FOR A MONTH TO INSURE MAINTENANCE WAS INCLUSIVE. THE IMPACTED SOIL NEAR THE

LIQUID RING SKID WAS REMOVED. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 157094

Corrective Action: MAINTAIN WEEDS ACCORDING TO RULE 606.

Date: 11/06/2021

Response: CA COMPLETED

Date of Completion: 11/04/2021

Operator Comment: THE VEGETATION THAT HAD ESTABLISHED NEAR THE WELL HEAD WAS CUT BACK AT LEAST 25 FEET FROM THE WELL FOR FIRE PROTECTION.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 157095

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. REPAIR LEAKING EQUIPMENT. 24 HOURS TO REPOVE OIL IN SKID, 30 DAYS TO REPAIR LEAKING EQUIPMENT.

Date: 11/22/2021

Response: CA COMPLETED

Date of Completion: 11/04/2021

Operator Comment: THE LEAK ON THE COMPRESSOR WAS REPAIRED AND THE FLUID ACCUMULATION WAS REMOVED 11/04/2021. A NEW LEAK WAS DETECTED PARTS WERE ORDERED AND REPLCED. UNIT WAS MONTORED FOR A MONTH TO INSURE MAINTENANCE WAS INCLUSIVE. THE IMPACTED SOIL NEAR THE LIQUID RING SKID WAS REMOVED. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: _____

Title: Sr. Environmental Tech. Date: 12/10/2021 9:08:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402895162	PHOTO LOG

Total Attach: 1 Files