

NEW ELK 36-07 API# 05-071-09235 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 04, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695105030



THE VEGETATION THAT HAD ESTABLISHED NEAR THE WELL HEAD WAS CUT BACK AT LEAST 25 FEET FROM THE WELL FOR FIRE PROTECTION.

NEW ELK 36-07 API# 05-071-09235 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 04, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695105030



MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING SKID WAS REMOVED
AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

NEW ELK 36-07 API# 05-071-09235 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 04, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695105030



THE FLUID ACCUMULATION THAT WAS FOUND INSIDE OF THE CONTAINMENT SKID OF THE LIQUID RING COMPRESSOR WAS REMOVED.

NEW ELK 36-07 API# 05-071-09235 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 03, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695105030



THE LEAK ON THE COMPRESSOR WAS REPAIRED AND THE FLUID ACCUMULATION WAS REMOVED 11/04/2021. A NEW LEAK WAS DETECTED PARTS WERE ORDERED AND REPLCED. UNIT WAS MONTORED FOR A MONTH TO INSURE MAINTENANCE WAS INCLUSIVE.