

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2021

Submitted Date:

12/10/2021

Document Number:

690102753

FIELD INSPECTION FORM

Loc ID 329399 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249484	WELL	SI	05/01/2021	OW	123-17287	BECCA D 3-12	PA

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected Facilities

Facility ID: 249484 Type: WELL API Number: 123-17287 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (Becca D 3-12); COGCC form 42 notice of start of plugging operations doc #402783724 received on 08/17/2021. COGCC form 44 (off location flowline abandonment) notice Doc #402736776 was updated to 11/16/2021. Flowline abandonment/ removal work has not been completed; flowline riser observed at PA well. OOSLAT observed on off location flowline valves (SI) at wellhead and inlet to heated horizontal separator (facility). No Noble Energy personnel were on location at the time of this field inspection.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 Doc #402885406 submitted 12/02/2021: Historical impacts were discovered during decommission activities where the flowline connected to the wellhead. Noble conducts routine AVO inspections of all oil and gas facilities.	maclarej	12/10/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102757	Well signage; Flowline riser (OOSLAT)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603529
690102758	Flowline inlet at HHS; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603530