

# Inspection Photos

API: 071-08723

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021

## Inspection Photos



**Photo 1.** Facing southeast along the access road. There is an erosion gully along the road side. The culvert at red arrow is filled in with sediment and the erosion gully was measured to be 4.5 ft. deep. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021

## Inspection Photos



**Photo 2.** Facing southeast further down the road. There is erosion along the road that needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021

## Inspection Photos



**Photo 3.** Stormwater is not properly diverted causing erosion of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021

## Inspection Photos



**Photo 4.** Facing north near the location. There is erosion along the road coming from the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021

Inspection Photos



**Photo 5.** Facing north toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08723 | Date: 12/9/2021