

Inspection Photos

Loc ID: 334233

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 1. Facing northeast at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 2. Facing south down the access road near county road 51. Red arrow points to where vehicle had driven off the designated road. This area down to the gate has not been restricted to prevent access by fence installation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 3. Facing northeast along the steep road. The road was graded however loose soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 4. Facing northeast along the steep road. The road was graded however loose soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 5. View of the aerial map between the two red arrows is the road shown in photos 1 thru 4. This road is steep and not stabilized as shown in the photos. This section of the road is not necessary for production of the well and needs to be recontoured and reclaimed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 6. Facing south along the access road. The red arrow shows where erosion is directing sediment onto the road. The side of the road needs to be seeded and stabilized. The road needs to be crowned and stabilized in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 7. Facing south along the access road. The road was graded however there is insufficient stabilization.



Photo 8. The shovel placed in the road surface shows loose soils and lack of stabilization.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos



Photo 9. Facing south along the access road. The road was graded however there is insufficient stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021

Inspection Photos



Photo 10. Facing north along the access road at the well site. The shovel placed in the road surface shows loose soils and lack of stabilization



Photo 11. The access road was bladed however the area of water pooling circled has not been stabilized and repaired. This area of the road should be crowned to divert water from the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 12. Facing southeast toward the LEFT FIELD #31-29 well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334233 | Date: 12/9/2021