

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2021

Submitted Date:

12/03/2021

Document Number:

699803829

**FIELD INSPECTION FORM**Loc ID 334067 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287563	WELL	PR	02/01/2021	GW	077-09170	WHITE 14-2(A140U)	PR
287564	WELL	SI	10/01/2019	GW	077-09169	WHITE 14-8(A140U)	PR
287565	WELL	PR	02/01/2021	GW	077-09168	WHITE 13-4(A140U)	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 12/1/21 at approximately 13:30 hours, I, Inspector Corey De Paolo,  
Conducted a follow up inspection at CAERUS PICEANCE LLC WHITE-68S96W /14NENE,  
Location #334067 in Garfield County Colorado.

Refer to document #699803024 inspection conducted on 5/4/21. Previous corrective actions have not been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a previous corrective action date of 8/4/21.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery	Date:	08/04/2021
Type	OTHER		
Comment:	Horizontal separator units include an attached storage tank. Storage tank is approximately 2'x3'x16' with an approximate capacity of 15 barrels. Based on the sight glass the storage tank appears to be full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 3		
Comment:	Pressure transducer located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on free flow no tools		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Chemical tanks	
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:	All wells on plunger lift	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			



Inspected Facilities									
Facility ID:	287563	Type:	WELL	API Number:	077-09170	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	287564	Type:	WELL	API Number:	077-09169	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	287565	Type:	WELL	API Number:	077-09168	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
		Culverts				
		Berms				
Compaction						
Sediment Traps						
Ditches						
		Sediment Traps				
		Ditches				
Gravel						
		Gravel				
				Material Handling And Spill Prevention		Chemical tanks

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to Signs/Markers for corrective actions.	depaoloc	12/03/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402887888	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596952</a>
699803830	Photos for Insp. #699803829	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596946</a>