

Inspection Photos
Location Name: Morgan A#1
Spill ID: 481051




Photo 1 – Downed fencing on 12/2/2021

Photo 2 – Remedial excavation on 12/2/2021

Inspection Photos
Location Name: Morgan A#1
Spill ID: 481051



COGCC Environmental Inspection
40.09696, -104.9864, 4954.2ft, 359°
12/02/2021 11:21:08 AM



COGCC Environmental Inspection
40.09696, -104.98641, 4954.1ft, 195°
12/02/2021 11:21:12 AM

Photo 3 – Stockpiled soils next to repair excavation on 12/2/2021.

Photo 4 – Large stockpile SE of remedial excavation on 12/2/2021

Inspection Photos
Location Name: Morgan A#1
Spill ID: 481051



Photo 5 – 12/2/2021: Foreground: Remedial excavation and downed fencing. Background: Additional soils stockpiles.

Photo 6 – Fencing repaired 12/9/2021

Inspection Photos
Location Name: Morgan A#1
Spill ID: 481051



Photo 7 – Sampling event 12/9/2021.

Photo 8 – Sampling event 12/9/2021.

Morgan 1A Spill

