

**Inspection Photos**  
**Location Name: Moser 1A**  
**Spill ID: 481067**




**Photo 1 – Site overview, silt fence damaged by wind, fencing down.**



**Photo 2 – Excavation. Fencing down.**



**Inspection Photos**  
**Location Name: Moser 1A**  
**Spill ID: 481067**



**Photo 3 – Groundwater in excavation**



**Photo 4 – Site overview; silt fence damaged by wind.**

**Inspection Photos**  
**Location Name: Moser 1A**  
**Spill ID: 481067**

**Photo 5 –**  
**Foreground: Fencing**  
**down around**  
**excavation,**  
**Background: Silt**  
**fence damaged by**  
**wind.**

