

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2021

Submitted Date:

12/13/2021

Document Number:

689501323**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
-, Marcom		primarycontractor@marcomllc.net	
, KPK		cogcc@kpk.com	All Inspections
Canfield, Chris		chris.canfield@state.co.us	
Rickard, Jeff		JRickard@kpk.com	KPK environmental
Gorka, Ray		RGorka@kpk.com	KPK environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478086	SPILL OR RELEASE	CL	01/15/2021		-	UPRR 43 PAN AM G Consolidation #2	EI

General Comment:

[This is an environmental inspection of Remediation Project 16131/Spill ID 478086 \(CL\). Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[At the time of inspection Operator and environmental contractor personal were on site to preform confirmation soil sampling.](#)

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: COGCC witnessed confirmation soil sampling on the excavation side walls. A third party contractor provided technical oversight for KPK crews during the sampling event. No stained soils were observed remaining insitu, but salt crusting was observed on excavation side walls near groundwater. An additional monitoring well had been installed east of the excavation area since the previous Form 27 submittal.

Corrective Action: **See Form 27 Doc No. 402855541 conditions of approval**

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____