

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Rig, pump and work tanks are grounded.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 422410 Type: WELL API Number: 069-06436 Status: SI Insp. Status: WK

Workover

Comment: MIRU KLX e-line, hold safety meeting, RIH with junk basket/guage ring to 6096' KB, POOH with tools, RIH with CIBP and set @ 6032' KB, POOH with setting tool, RIH with dump bailer and spot 2 sxs of cement slurry on top of CIBP, POOH with dump bailer, RDMO e-line.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697004947	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605741