

GOLDEN EAGLE 20-05X API# 05-071-08637 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202344



THE IMPACTED SOIL ON THE GROUND NEAR THE DRIP RISER ALONG THE MAIN ROAD WAS CLEANED UP. NO ENVIRONMENTAL IMPACTS WERE DISCOVERED.

GOLDEN EAGLE 20-05X API# 05-071-08637 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 13, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202344



THE SOURCE OF THE WATER THAT WAS FOUND ON THE ROAD SURFACE IS FROM A NATURAL SPRING THAT FLOWS YEAR ROUND ADJACENT TO THE LEASE ROAD.

GOLDEN EAGLE 20-05X API# 05-071-08637 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 13, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202344



THE VEGETATED BAR DITCH WAS DOMINATED TO RECEIVE WATER FROM THE SPRING. THIS FLOWS DOWN TO THE EPHEMERAL CHANNEL NORTH OF THE GE 20-05X WELL PAD.

GOLDEN EAGLE 20-05X API# 05-071-08637 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 13, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202344



THE VEGETATED BAR DITCH WAS DOMINATED TO RECEIVE WATER FROM THE SPRING WHICH HAS BEEN THE NORMAL COURSE OVER THE YEARS FOR THE SPRING.