

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2021

Submitted Date:

12/13/2021

Document Number:

696303838**FIELD INSPECTION FORM**Loc ID 421165 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------|---------------------------------|
| , | | EHSRC@bonanzacrk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 421168 | WELL | TA | 07/12/2019 | GW | 123-32833 | Antelope 41-31 | TA |
| 421330 | WELL | TA | 07/03/2019 | GW | 123-32888 | Antelope 31-31 | TA |
| 430259 | WELL | SI | 07/01/2021 | OW | 123-36105 | Antelope 41-44-31HZ | SI |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|---------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Adequate (x3) | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unmarked Riser at 41-44-31HZ Wellhead; see photos | | |
| Corrective Action: | Comply with Rule 606 | Date: | 12/17/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|----------------------|-------|-----------------|
| Type: Bradenhead | # 3 | | corrective date |
| Comment: | Appear to be surface | | |
| Corrective Action: | | Date: | |
| Type: Other | # 2 | | |
| Comment: | TA Wellheads | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 421168 Type: WELL API Number: 123-32833 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - MIT: 05.06.2021

Corrective Action: _____ Date: _____

Facility ID: 421330 Type: WELL API Number: 123-32888 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - MIT: 05.06.2021

Corrective Action: _____ Date: _____

Facility ID: 430259 Type: WELL API Number: 123-36105 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| Routine Field Inspection. Unmarked Riser at 41-44-31HZ | petrie | 12/13/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696303839 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605867 |