

TEP
RWF 333-18
Location # 335133



location



location



TEP
RWF 333-18
Location # 335133



location



Load lines lacking bull plugs/caps

TEP
RWF 333-18
Location # 335133



Load lines lacking bull plugs/caps



Lack of stabilization/compaction

TEP
RWF 333-18
Location # 335133



Dec 13, 2021 at 1:38:24 PM
+39.523869, -107.930323 ±4.74m
COGCC

Insulation



Dec 13, 2021 at 1:38:47 PM
+39.523869, -107.930323 ±4.74m
COGCC

Insulation



TEP
RWF 333-18
Location # 335133



Rope and insulation



Sight glass shows fluid in storage tank

TEP
RWF 333-18
Location # 335133



Sight glass shows fluid in storage tank



Unknown contents bucket

TEP
RWF 333-18
Location # 335133



Unknown contents bucket

