

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/13/2021

Submitted Date:

12/14/2021

Document Number:

690102766

FIELD INSPECTION FORM
 Loc ID 323043 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412015	WELL	SI	10/01/2020	OW	123-30353	SAWDEY 5-30	PA

General Comment:
 COGCC Engineering Integrity Inspection; Flowline Inspection
 Photos uploaded

Inspected Facilities

Facility ID: 412015 Type: WELL API Number: 123-30353 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	2 of Lines	
----	---------------------	------------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Sawdey 5-30) is plugged and abandoned; Cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402792366 received 08/26/2021. COGCC form 42 notice of flowline abandonment completed notice doc #402896233 received on 12/13/2021. Wellhead flowline (OLF) is approx 1350' in length; (2) flowline risers were observed in an open excavation at the (PA) wellhead during this field inspection. (1) 2" CS production flowline and (1) 1" HDPE gas supply flowline; flowline abandonment has not been completed (in progress). The facility/ battery is shared; excavation observed in the area of flowlines at inlet to HHS. Excavation/ remediation work (wellhead/ facility) is in progress.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402892792 received on 12/09/2021: On December 8, 2021, historical soil impacts were discovered during removal of the risers at each end of the flowline associated with the Sawdey 5-30 wellhead. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	12/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690102769	Signage at wellhead (PA)	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607077
690102770	PA well (cut & cap); flowlines exposed in excavation	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607078
690102771	Excavation at facility; flowline manifold at HHS	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607079