

Inspection Photos  
Operator: Morningstar  
API: 007-06308  
Date: 12/13/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation appears sparse, but progressing in a largely grazed condition. This should be assessed during the active growing season.



Photo 3. View of dense Russian thistle debris observed within the southern project area. Inset shows a Russian olive tree that needs to be removed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with blue grama, cholla, and snakeweed in the understory.