

Inspection Photos  
Operator: Simcoe  
API: 007-06325  
Date: 12/13/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and sand dropseed. Portions of the slope remain sparse and need to be monitored.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of materials stored within the interim reclamation areas, need to be removed.



Photo 4. View of reference area (beyond fenceline) comprised irrigated grass field. Vegetation is largely dormant and grazed at this time.